

## **Quick Instruction Manual for** USB-C™/Thunderbolt™ 3 to **Gigabit Ethernet Adapter** (Part #X40091)

- 1- Please remove the USB-C™/Thunderbolt™ 3 product from the package.
- 2- Connect the USB-C™/Thunderbolt™ 3 port to your MacBook or USB-C™/Thunderbolt™ 3 ready computer.
- 3- Connect your ethernet cabel to the other end of adapter. You should see the following LED Status!

LED	Color	Description
Left LED	Amber or Green	Speed indicator:  • Amber on-Operating as a Gigabit connection (1000 Mbps).  • Green on-Operating as a 100-Mbps connection.  • Off-Operating as a 10-Mbps connection.
Right LED	Green	Link/Activity Indicator:  • Blinking-There is activity on this port.  • Off-No link is established.

4- The cable should now be linked and ready to use.

Let us know how you use our products, share with us at!

On Facebook, Instagram, Pinterest, Google Plus, or any other media outlet.













Please email us with any questions or feedback you might have about our products to support@ezq.com.